

**TCAT at Murfreesboro -Heating, Ventilation, A/C Program  
Fees and Supplies Estimated Cost  
2020-2021**

First Term		TUITION / FEES	BOOKS	SUPPLIES	TOTALS
Tuition:	Tuition	\$1,312.00			
Fees:	EPA 608 Universal Certification Test Fee	\$25.25			
	OSHA	\$25.25			
Books:	9780357477267 - Refrigeration & Air Conditioning Technology, 9th + MindTap, 4 term Printed Access Card		\$176.00		
	EPA Certification Exam Preparation Manual		\$5.00		
Supplies:	<b>*Cost estimate for tools needed - prices may vary*</b>			\$825.00	
	<b>Tools:</b>				
	Nut Driver Set	Crimping Pliers			
	Screw Driver Set	Inspection Mirror			
	6" Adjustable Wrench	Manifold with Ball Valve Hoses			
	8" Adjustable Wrench	Safety Glasses			
	8" Side Cutter Pliers	Safety Gloves w/ Leater Palms			
	Needle Nose Pliers	Safety Knee Pads			
	5/16" x 1/4" Reversible Ratchet	Tool Bag			
	Wire Stripers	Multimeter (Fieldpiece SC260)			
<b>TOTAL - 1st Term:</b>		<b>\$1,362.50</b>	<b>\$181.00</b>	<b>\$825.00</b>	<b>\$2,368.50</b>
Second Term		TUITION / FEES	BOOKS	SUPPLIES	TOTALS
Tuition:	Tuition	\$1,312.00			
Fees:					
Books:					
Supplies:	<b>*Please see instructor for list and cost estimate for second term tools*</b>			\$1,124.00	
	Safety glasses			\$2.00	
<b>TOTAL - 2nd Term:</b>		<b>\$1,312.00</b>	<b>\$0.00</b>	<b>\$1,126.00</b>	<b>\$2,438.00</b>
Third Term		TUITION / FEES	BOOKS	SUPPLIES	TOTALS
Tuition:	Tuition	\$1,312.00			
Fees:					
Books:					
Supplies:	<b>*Please see instructor for list and cost estimate for third term tools*</b>			\$758.00	
	Safety glasses			\$2.00	
<b>TOTAL - 3rd Term:</b>		<b>\$1,312.00</b>	<b>\$0.00</b>	<b>\$760.00</b>	<b>\$2,072.00</b>

**Fees, books, and supplies prices are subject to change.**

	<b>GRAND TOTAL</b>	<b>\$3,986.50</b>	<b>\$181.00</b>	<b>\$2,711.00</b>	<b>\$6,878.50</b>
TRA and other agencies please allow an estimated increase of 20% of possible increases in Tuition, Fees, Books, Supplies & Tools.				20% Increase	\$1,375.70
				<b>Total</b>	<b>\$8,254.20</b>

\*\*Bookstore does not carry these supplies so please make arrangements to get your supplies from outside sources\*\*